

## ASTM F2992/F2992M-15 STANDARD TEST METHOD FOR MEASURING CUT RESISTANCE IN PROTECTIVE CLOTHING



200 - 499 grams to cut Light cut hazards



500 - 999 grams to cut Light/medium cut hazards



1000 - 1499 grams to cut Light/medium cut hazards



1500 - 2199 grams to cut Medium cut hazards



2200 - 2999 grams to cut Medium/high cut hazards



3000 - 3999 grams to cut High cut hazards



4000 - 4999 grams to cut High cut hazards



5000 - 5999 grams to cut High cut hazards



6000+ grams to cut High cut hazards

